

# Global Ventures Australia

ABN 77 065 255 763

## Eco-Core White Birch Multiply with High Pressure Laminates

### CARE AND MAINTENANCE

#### SECTION 1 COMPANY IDENTIFICATION

<b>Company Name</b>	Global Ventures Australia Pty Ltd
<b>Address</b>	Unit 13 / 22 Beaumont Road Mount Kuring Gai NSW 2080 Australia
<b>Phone</b>	+ 61 2 9457 7171
<b>Website</b>	www.ecocore.com.au
<b>Email</b>	enquiries@globalventures.com.au

#### SECTION 2 CARE AND MAINTENANCE

<b>Storage and Handling</b>	<p>Sheets should be stored flat in a clean and dry environment away from water, moisture, humidity and direct sunlight. It is best stored in the original packaging with cover sheets top and bottom until it is needed.</p> <p>Please take care to remove the plastic protective film after installation and ALL trades have completed works. Be careful of any dusts that may be sitting on the surface as they should be gently removed by using a soft and dry duster or micro fibre cloth. If the dust is rubbed into the surface it can become embedded in the surface and leave a mark.</p>
<b>Cleaning and Maintenance</b>	<p>Wipe the surface of the laminate with a soft, clean, water dampened cloth, wring out excess water. Follow with a clean soft dry cloth and wipe until surface is dry. Never use abrasive cleaning materials or sharp implements. Do not use any corrosive or strong solvents that may damage the surface. Avoid the use of acetone or trichloroethylene for cleaning purposes. Use of abrasive cleaners, powders, scouring pads, steel wool, sandpaper etc. can damage the finish and make the surface susceptible to staining. Accidental spills or splatters from harsh materials should be wiped off immediately, and the area cleaned thoroughly with a damp cloth, always use protective gloves. Examples of these materials are: ceramic cooktop cleaners, tub and tile cleaners, chlorine bleach, oven cleaners, and other harsh detergents. Do not place hot objects such as kettles, pots or appliances directly onto the laminate surface, use a trivett or a cork board. Do not cut directly on the surface as it may leave a permanent mark.</p>